VIA® USB 3.0 Driver Package Release Notes

2014-07-01

Support Platforms Component version inside this package Notices Update of this Release Installation and Uninstall Known Issues Limitations Revision History DISCLAIMER

Support Platforms

Hardware:

VIA XHCI Host Controller

Operating System:

Microsoft Windows© 8.1 X86/X64, Windows© 8 X86/X64, Windows© 7 X86/X64, Windows© Vista X86/X64

/Back to top

Component version inside this package

| Component | Version |
|--|--|
| VIA USB 3.0 Driver for Windows 8/8.1 | Port Driver (Xhcdrv.sys): 6.1.7600. 4701 Hub Driver (Viahub3.sys): 6.1.7600. 4701 |
| VIA USB 3.0 Driver for Windows 7 | Port Driver (Xhcdrv.sys): 6.1.7600. 4701 Hub Driver (Viahub3.sys): 6.1.7600. 4701 |
| VIA USB 3.0 Driver for Windows Vista | Port Driver (Xhcdrv.sys): 6.1.7600. 4701 Hub Driver (Viahub3.sys): 6.1.7600. 4701 |
| VIA USB 3.0 UASP Client Driver | 6.1.7600. 4002 |
| VIA USB 3.0 UASP Transfer Mode Utility | 1.0.0.15 |

Back to top

Notices

1. In this driver package, it contains both the drivers for USB 3.0 host controller and UASP storage device driver.

- 2. Please update your VIA XHCI host controller PCIe Card with latest version of firmware which can support UASP before install this driver.
- 3. This UASP driver needs to work together with the "VIA USB 3.0 Speeder" utility.

Back to top

Update of this Release

1. Fix specific Figerprint keyboard compatibility issue.

Back to top

Installation and Uninstall

1. Please update your VIA XHCI Host Controller PCIe Card to latest version of firmware before you install this driver.

2. Please use the setup program to install/uninstall the driver for XHCI host controller and its root hub device.

3. Following is the instruction for silent mode driver installation/removal.

| Command line | Execution |
|--|---|
| VIA_XHCI_Driver_V4.70C.exe /silent | Silent Installation |
| VIA_XHCI_Driver_V4.70C.exe /verysilent | Very Silent Installation(system will reboot automatically) |

VIA_XHCI_Driver_V4.70C.exe /verysilent /norestart Very Silent Installation(system won't reboot)

4. Manual Install & Manual Un-Install

4.a Manual Install:

Step 1. Select "VIA USB eXtensible Host Controller" in the Device Manager. Choose the Driver Tab. Click the "Update Driver" icon.

Select "Xhcdrv.sys" which locates in the driver folder.

Step 2. Select "VIA USB 3 Root Hub" in the Device Manager. Choose the Driver Tab. Click the "Update Driver" icon.

Select "Viahub3.sys" which locates in the driver folder.

Step 3. Select "VIA USB 2 Hub" in the Device Manager. Choose the Driver Tab. Click the "Update Driver" icon.

Select "Viahub3.sys" which locates in the driver folder.

Step 4. Restart your system.

4.b Manual Un-Install:

Step 1. Select "VIA USB 2 Hub" in the Device Manager. Choose the Driver Tab. Click the "Uninstall" icon.

Select OK for "Confirm Device Uninstall".

Step 2. Select "VIA USB 3 Root Hub" in the Device Manager. Choose the Driver Tab. Click the "Uninstall" icon.

Select OK for "Confirm Device Uninstall".

Step 3. Select "VIA USB eXtensible Host Controller" in the Device Manager. Choose the Driver Tab. Click the "Uninstall" icon.

Select OK for "Confirm Device Uninstall".

Step 4. Restart your system.

Back to top

Known Issues

Back to top

Limitations

Back to top

Revision History

| Version | Release Date | Comments |
|----------------|--------------|--|
| V1.00 A (WHQL) | 2010-12-08 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.10 A (WHQL) | 2010-12-31 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.20 A (WHQL) | 2011-01-12 | VIA Windows 7 and Windows XP XHCI Driver (Logo'd) |
| V1.30 A (WHQL) | 2011-03-02 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.40 A (WHQL) | 2011-03-11 | VIA Windows 7, Vista and XP XHCI Driver (Logo'd) |
| V1.41 A (WHQL) | 2011-03-21 | Update WinXP Logo'd driver |
| V1.50 A (WHQL) | 2011-05-25 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.60 A (WHQL) | 2011-05-31 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.60 B (WHQL) | 2011-06-21 | VIA Windows 7, XP XHCI Driver (Logo'd) |
| V1.70 A (WHQL) | 2011-09-06 | VIA Windows 7 XHCI Driver (Logo'd) |
| V1.80 C (WHQL) | 2012-01-06 | VIA Windows 7 and Windows XP XHCI Driver (Logo'd) |
| V1.90 A (WHQL) | 2012-02-08 | VIA Windows 7 and Windows XP XHCI Driver (Logo'd) |
| V2.10 A (WHQL) | 2013-01-14 | WHQL Driver (Win8, Win7, Vista, XP: V2.108), Non-WHQL (Client:V4.00Beta1) |
| V2.10 B (WHQL) | 2013-01-21 | WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |
| V2.10 C (WHQL) | 2013-01-24 | WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |
| V2.10 D (WHQL) | 2013-02-21 | WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |
| V2.10 E (WHQL) | 2013-04-11 | ●WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |

| V2.10 F (WHQL) 2013-05-08 •WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) V2.10 G (WHQL) 2013-06-03 •WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) V4.10 A (WHQL) 2013-07-31 •WHQL Driver (Win8, Win7, Win XP: V4.10Beta4; Client:V4.002) V4.20 B (WHQL) 2013-09-03 •WHQL Driver (Win8.1, Win8, Win7, Win XP: V4.201; Client:V4.002) V4.30 A (WHQL) 2013-11-12 •WHQL Driver (Win8.1, Win8, Win7; V4.301; Client:V4.002) V4.40 D (WHQL) 2014-01-21 •WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista; V4.501; Client:V4.002) V4.70 C (WHQL) 2014-07-01 •WHQL Driver (Win8.1, Win8, Win7, Vista; V4.701; Client:V4.002) | | | |
|--|----------------|------------|---|
| V4.10 A (WHQL) 2013-07-31 •WHQL Driver (Win8, Win7, Win XP: V4.10Beta4; Client:V4.002) V4.20 B (WHQL) 2013-09-03 •WHQL Driver (Win8.1, Win8, Win7, Win XP: V4.201; Client:V4.002) V4.30 A (WHQL) 2013-11-12 •WHQL Driver (Win8.1, Win8, Win7: V4.301; Client:V4.002) V4.40 D (WHQL) 2014-01-21 •WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista; V4.501; Client:V4.002) | V2.10 F (WHQL) | 2013-05-08 | ●WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |
| V4.20 B (WHQL) 2013-09-03 •WHQL Driver (Win8.1, Win8, Win7, Win XP: V4.201; Client:V4.002) V4.30 A (WHQL) 2013-11-12 •WHQL Driver (Win8.1, Win8, Win7: V4.301; Client:V4.002) V4.40 D (WHQL) 2014-01-21 •WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista; V4.501; Client:V4.002) | V2.10 G (WHQL) | 2013-06-03 | ●WHQL Driver (Win8, Win7, Vista, XP: V2.108; Client:V4.002) |
| V4.30 A (WHQL) 2013-11-12 •WHQL Driver (Win8.1, Win8, Win7: V4.301; Client:V4.002) V4.40 D (WHQL) 2014-01-21 •WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista; V4.501; Client:V4.002) | V4.10 A (WHQL) | 2013-07-31 | ●WHQL Driver (Win8, Win7, Win XP: V4.10Beta4; Client:V4.002) |
| V4.40 D (WHQL) 2014-01-21 •WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista: V4.501; Client:V4.002) | V4.20 B (WHQL) | 2013-09-03 | ●WHQL Driver (Win8.1, Win8, Win7, Win XP: V4.201; Client:V4.002) |
| V4.50 A (WHQL) 2014-01-24 •WHQL Driver (Win8.1, Win8, Win7, Vista: V4.501; Client:V4.002) | V4.30 A (WHQL) | 2013-11-12 | •WHQL Driver (Win8.1, Win8, Win7: V4.301; Client:V4.002) |
| | V4.40 D (WHQL) | 2014-01-21 | ●WHQL Driver (Win8.1, Win8, Win7, Vista, XP: V4.402; Client:V4.002) |
| V4.70 C (WHQL) 2014-07-01 •WHQL Driver (Win8.1, Win8, Win7, Vista: V4.701; Client:V4.002) | V4.50 A (WHQL) | 2014-01-24 | ●WHQL Driver (Win8.1, Win8, Win7, Vista: V4.501; Client:V4.002) |
| | V4.70 C (WHQL) | 2014-07-01 | ●WHQL Driver (Win8.1, Win8, Win7, Vista: V4.701; Client:V4.002) |

Back to top

DISCLAIMER

Information in this document is provided in connection with VIA USB 3.0 driver package. VIA Technologies assumes no responsibility for any errors in this document. Any part of document MUST NOT be reproduced, transmitted, or translated into any language, or in any form without the prior written permission of VIA Technologies Inc.

VIA may make changes to specifications and product descriptions at any time, without notice. Copyright © VIA Technologies, Inc. 2009-2013

Back to top

All copyrights are reserved by VIA Technologies, Inc. http://www.via.com.tw/en